Rimu Bay Realty

Healthy homes compliance statement: 32 Wood Street, Rimu Bay

Prepared for the landlord. Assessed 2 July 2025.

SAMPLE

Standard	Status	Detail
Heating	Complies	Heat pump in the living room, 6.0 kW heating capacity.
Insulation	Complies	Ceiling R3.6, underfloor R1.3.
Ventilation	Complies	Extract fans in the kitchen and bathroom. Opening windows in every habitable room.
Moisture and drainage	Complies	Ground vapour barrier. Gutters and downpipes in working order.
Draught stopping	Complies	No unreasonable gaps. Open fireplace sealed.

A made-up statement for this sample page.

SAMPLE